

## How to Mount Eris Front Projection Film

To apply this adhesive-backed screen to windows, glass, acrylic or polycarbonate substrates, have the following items ready to use:

- Projection Film
- Spray bottle with 50 ounces water to 1 table-spoon Johnsons baby shampoo mixture
- Clear Max rubber-blade squeegee
- Dry, soft cloth (preferably microfiber)
- Electrical tape to mark the boundaries of the screen (if smaller than the substrate)

For instructions on applying film to porous substrates such as drywall, please contact a Spyeglass representative.

### !!NOTE!!

This film does not have a protective outer layer! If your squeegee is too hard, or has dirt on it you will scratch on the screen during installation. We recommend a 5-Inch Clear Max Blade. Please use caution.

1. Thoroughly clean the substrate of dirt, dust and oils using soapy solution, then squeegee the excess solution from the substrate.
2. If the screen is smaller than the substrate use electrical tape to mark the area that the screen will be applied to. (If the substrate is clear, this can be marked from the opposite side of the substrate.)
3. Peel the adhesive release liner from the screen while spraying the adhesive-side of screen and the surface of the substrate with soapy water solution.

**NOTE: Make sure to peel the release liner**

## SpyeFront Installation Instructions

evenly from the corners to prevent the screen from creasing or folding over on itself.

4. Place the screen carefully on the substrate while aligning the edges to the tape.

5. Spray front of film with soapy water solution. This will allow the squeegee to glide more smoothly over the top of the screen and help prevent scratching.

6. Remove the water and any air bubbles with the squeegee blade by squeegeeing the water from the center of the screen toward the edges.

### !!NOTE!!

Purge ALL water and air from beneath the film during installation. Any trapped water or air will not evaporate on its own and will cause bubbling.

7. Remove the excess water with a dry, soft cloth.

8. Remove the tape if necessary.

## Care & Cleaning

To clean, use a diluted solution of 1 part window cleaner (Windex, Glass Plus, etc.) to 10 parts water. Spray cleaner directly onto cloth until cloth is moistened, not oversaturated. Do not spray directly onto film. Wipe down screen and immediately repeat with a clean, dry, soft cloth. To keep screen in good condition, do not use any cleaners with ammonia, alcohols, or industrial cleaning fluids!